

# **FREEZE WARNING**

**TO PROTECT YOUR PROPERTY AND AVOID LIABILITY FOR FREEZE DAMAGE TO THE RV PARKS WATER HYDRANTS ONE OF THE FOLLOWING STEPS MUST BE TAKEN**

**A) FILL YOUR ON BOARD WATER STORAGE TANKS** AND DISCONNECT FROM THE PRESSURIZED WATER SYSTEM **CLOSE THE HYDRANT AND REMOVE YOUR WATER HOSE. LOWER THE RED HYDRANT HANDLE, AND OPEN THE ROUND VALVE ON TEE**  
**OR**

**B) INSTALL ELECTRICAL HEAT TAPE** BEGINNING AT THE ***BASE OF HYDRANT*** (AT GROUND) LEADING ALL THE WAY TO YOUR WATER INLET ON YOUR RV. **PLEASE MAKE SURE THE HEAD OF THE HYDRANT IS ALSO INSULATED.** FIBERGLASS WRAPPED IN PLASTIC OR NEOPRENE INSULATION WORKS WELL. PLUG THE HEAT TAPE INTO OUR ELECTRICAL BOX AND VERIFY OPERATION.

**FAILURE TO PROTECT THE PRESSURIZED WATER SYSTEM WILL RESULT TO DAMAGE TO YOUR RV WATER SUPPLY AND CREATE HYDRANT REPLACEMENT REPAIR WORK, WHICH YOU WILL BE OBLIGATED FOR.**

**HYDRANT REPLACEMENT WILL BE CHARGED STARTING AT \$350.00**

**PLEASE HELP PROTECT YOUR PROPERTY AND OURS, FOLLOW ONE OF THE ABOVE LETTING THE WATER RUN IN YOUR CAMPER IS NOT AN ACCEPTABLE METHOD OF PREVENTION. THIS CAUSES EXCESS USE OF WATER AND IS A WASTE OF RESOURCES.**

**IF YOU ARE IN A LONG-TERM SITE THAT HAS A WATER PIT, THEN PLEASE CONNECT TO THE HYDRANT IN THE BOTTOM OF THE PIT. OTHERWISE FOLLOW THE ABOVE INSTRUCTIONS.**

**Questions? Just give us a call 816-781-7724**

# **ADVERTENCIA DE CONGELAMIENTO**

**PARA PROTEGER SU PROPIEDAD y evitar responsabilidad por danos por congelacion a los hidrantes de los parques de RV, debe hacer una de las siguientes cosas:**

**A) Llene los tanques de almacenamiento de agua a bordo y desconectese del Sistema de agua a presion, cierre la boca de riego y retire la manguera de agua. Sujete la manija de la boca de riego roja y abra la manija redonda de valvular en la valvular en T.**

**0**

**B) Instale la cinta de color electrica comenzando en la base de la boca de riego (a nivel del suelo) y yendo hasta su entrada de agua en su RB. Por favor, asegurese de que la Cabeza de la boca de riego Tambien este aislada. (La fibra de vidrio envuelta en plastic o el aislamiento neopreme funciona bien) Enchufe su cinta termica en nuestra caja electricca y verifique que este funcionando correctamente.**

**EL NO PROTEGER LAS LINEAS DE AGUA RESULTARA EN DANOS A SU SUMINISTRO DE AGUA RB Y CAUSARA TRABAJOS DE REPARACION DE REEMPLAZOS DE HIDRANTES DE LOS CUALES SERA RESPONSIBLE DE PAGAR.**

**EL CARGO DE REEMPLAZO DEL HY6DRANTE COMIENZA A \$350.00 usd**

**SI NO SE SIGUEN LAS INSTRUCCIONES MENCIONADAS ANTERIORMENTE, EL HYDRANTE DE AGUA ESTA BLOQUEADO Y NO TIENE MAS TEIMPO EL USO DE AGUA DEL CAMPAMENTO.**